

PERFECTION PLUS
 #9 TRIGON PLACE
 LITTLE ROCK, AR. 72209

{501}565-1911

Year	2005	Engine	3.2L	Page 1	
Make	PORSCHE	TransInfo			
Model	BOXSTER S	Job Type	INVOICE	Date Started	09/11/20
License #		Odometer In	0	Date Completed	09/11/20
Vin #	WP0CB29885U731805	Odometer Out	119472	Invoice #:	11543

Part Number	Qty	Description	Price	Extension
-------------	-----	-------------	-------	-----------

LABOR

PRE-PURCHASE INSPECTION: 192.00 RIC

PAINT WORK ON FRONT BUMPER, REAR
 BUMPER, LEFT REAR SIDE, RIGHT REAR IN
 FRONT OF TIRE, SMALL DENT, CENTER OF
 FRONT BUMPER TRIM LOOSE

CUP HOLDER COVER WILL NOT CLOSE,
 PASSENGER WINDOW SWITCH WON'T GO UP,
 FRONT TRUNK LOCK INOPERABLE, NEEDS
 REAR TRUNK STRUT, RADIO INOPERABLE

FRONT PADS AND ROTORS WITHIN 20% WEAR
 LEFT, REAR PADS AND ROTORS WITHIN 40%
 WEAR, TIRES FROM 2018

NO DEBRIS IN OIL FILTER

VEHICLE RUNS AND DRIVES CORRECTLY

SHOP SUPPLIES.

3.84

LABOR

195.84

Pay Method = VISA 213.47

<u>Sub Total</u>	<u>195.84</u>
<u>Sales Tax</u>	<u>17.63</u>
<u>Total</u>	<u>213.47</u>

I hereby authorize the above repair work to be done along with any necessary materials. You may operate the vehicle for purposes of testing at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount or repairs thereto. I have read and understand this invoice including comments.